



47TH TURBOMACHINERY & 34TH PUMP SYMPOSIA
HOUSTON, TEXAS | SEPTEMBER 17-20, 2018
GEORGE R. BROWN CONVENTION CENTER

Case Study on investigation and resolution of Dry Gas Secondary Seal Failure

Girish Kamal
Fairul Azam Bin Salehan

Presenter/Author bios

Girish Kamal

Principal Rotating
Equipment Engineer

Girish Kamal is working as Principal Rotating Equipment Engineer with the Centre of Excellence Division of PETRONAS Carigali Sdn. Bhd. in Kuala Lumpur. He has more than 28 years experience in the Oil and Gas Industry in the fields of rotating equipment management for onshore and offshore applications including specifications, design approvals, testing, inspection, commissioning, installation, maintenance and technical services.

Fairul Azam Bin Salehan

Senior Rotating
Equipment Engineer

Fairul Azam Bin Salehan is working as Senior Rotating Equipment Engineer with PETRONAS Carigali Sdn Bhd. He has more than 12 years experience in maintenance and reliability of Turbomachinery and rotating equipment. He has carried out RCAs for various rotating equipment failures.



Abstract

Dry Gas (DGS) Secondary Seal installed on one of the Flash gas compressor unit at an onshore gas treatment facility failed resulting in equipment downtime and process gas flaring.

During detailed tear down inspection, primary seal was found heavily contaminated with sticky oily substance that reached into the secondary seal leading to contact between the seal faces causing thermal cracks.

This case study will present the problem encountered, root causes analyzed, solutions implemented, results and lessons learnt.



Contents

1. Machine Details
2. Problem Statement
3. Dry Gas Seal System Schematic
4. Chronology of incident
5. Failure Observations & DGS Inspection Results
6. Root Cause Failure Analysis
7. Solutions Implemented
8. Results
9. Lessons Learnt



Machine Details

Flash Gas Compressor (Two stages) Electric Motor Driven

<u>Operating Data:</u>	<u>Stage 1</u>	<u>Stage 2</u>
Suction Pressure:	6.5 bara	20.4 bara
Suction Temp.:	55.5 deg C	49.9 deg C
Discharge Pressure:	21.28 bara	62.8 bara
Discharge Temp.:	139.4 deg C	142.5 deg C
Inlet Volume:	2740 m3/hr	781 m3/hr
Mol. Wt.:	29 kg/kmol	
Speed:	14853 rpm	
Train Power:	2010 KW	

**Unit was installed & commissioned in 2012
but running in intermittent operation.**



Problem Statement



- Flash Gas Compressor unit fitted with Tandem Dry Gas seal with intermediate labyrinth.
- Both the Primary & Secondary high vent pressures are monitored with alarm as well as shutdown safeguards provided therein.
- High vent pressure alarm appeared on the Secondary Seal (non drive end) during operation in Jan-2014.
- Eventually the compressor unit tripped on Secondary seal NDE high high vent pressure limit after approx. 50 minutes.
- **Dry Gas Seal failure.**



Dry Gas Seal System Schematic/Details

DGS Details:

- Tandem arrangement with intermediate labyrinth.
- Bi Directional T-Groove Patterns.
- Seal Gas Heater to maintain seal gas supply temperature.
- Seal gas supply with 3um duplex coalescing filter assembly (Beta Ratio ≥ 200).
- Plant nitrogen being used as buffer gas for intermediate seal as well as separation gas for bearing housing.
- Buffer/Separation Nitrogen gas filtration with 3um duplex filters (Beta Ratio ≥ 200).



Chronology of Incident

**28/01/14
(01:02AM)**

**Secondary seal
NDE high vent
pressure alarm
appeared**

**28/01/14
(01:51AM)**

Secondary seal
NDE vent
pressure
exceeded the
high-high limit
and compressor
tripped

**28/01/14
(02:28AM)**

Attempted to
start the unit but
failed due to
secondary NDE
pressure high-
high shutdown


**29/01/14
(09:00AM)**

Inst. Checks
conducted on
the Secondary
seal NDE Vent
pressure
transmitters
confirmed
genuine reading

**29/01/14
(01:00PM)**

Verified
historical data
trending from
DCS and
confirmed DGS
failure

Historical Trending of NDE Seal Pressure Monitoring



Failure Observations

1. Carbon dirt / soot inside the Seal Gas Filter Casing.



2. Dirty Seal Gas Coalescing Filter.



3. Contaminated Seal Gas Supply piping.



Failure Observations

4.Foreign material inside the seal gas heater.



5.Very dirty Primary seal.




6.Contaminated DGS casing.





Failure Observations & DGS tear down Inspection Results

7. Condensate deposits inside the seal casing and outside the DGS cartridge.






8. Seal Ring (#1) and Mating Ring (#4) from primary seal - Contaminated with rust like substance and liquid and contact traces on the sealing surface.



DGS tear down Inspection Results

9. Seal Ring (#11) and Mating Ring (#44) from secondary seal

Heavy contract traces on the sealing surface and seal face broken in several parts



10. Seal element (#2) from primary sealing and seal element (#12) from secondary sealing -


Heavily contaminated with rust like substance and liquid. Pitting marks on the surface.



Root Cause Failure Analysis

Direct Causes:

- Heavy face contact with wear on the rotating face sealing surface of the Secondary Seal.
- Presence of liquid dusty substance in the secondary seal gap that caused the face contact.
- Heavy contamination with rust like particles and traces of liquid in the Primary Seal/Process side.



Root Cause Failure Analysis

Indirect Causes:

- Poor seal gas supply quality due to inadequate filtration.
- Dirty seal gas supply lines and seal gas heater (improper flushing).
- Dirty and un-cleaned process gas coming in contact with the seal mating faces.
- Hydrate and liquid formation (condensation) on seal faces while seal gas expanding and loss of dew point margin.



Solutions Implemented

1. Seal Gas conditioning to prevent liquid condensation.
2. Maintaining effective heat tracing for seal gas supply piping.
3. Cleaning of the seal gas/buffer gas filter housing.
4. Cleaning/flushing/blowing of the seal gas supply piping and heater using N2.
5. Replacement of seal gas coalescing filters and N2 buffer/separation gas filters.
6. Weekly Equipment Basic Care (EBC) program for the seal gas supply/vent lines & coalescing filters.
7. SAP Mplan re-scheduling to 8K PM (from 16K PM) for the seal gas filters replacement & Filter DP transmitter tapping line/needle valve inspection.
8. Ensuring no occurrence of liquid carry over during pigging activity.



Results

- ✓ DGS & Compressor system uptime and reliability improvement with no more Dry Gas Seal failures post solutions implementation.
- ✓ MTBF > 04 years and still counting....



Lessons Learnt


- ❑ Sufficient seal gas dew point margin throughout the entire seal gas system to prevent hydrate and liquid formation on seal faces.
- ❑ Adequate QA/QC checks during pre-commissioning activities especially during seal gas piping cleaning and flushing.
- ❑ Design, Operation & Maintenance considerations for the entire seal gas system to ensure reliable DGS operation.
- ❑ Dry Gas Seal health monitoring including tracking and trending of Primary as well as Secondary seal vent pressures/flows.
- ❑ Eliminate process interruption (e.g. during pigging) to prevent contaminants going into the sealing system.



Back-Up Slides



Root Cause Failure Analysis




X Cause Ruled out based on factual information



? Possible but could not be validated





Root Cause Failure Analysis



Root Cause Failure Analysis



Root Cause Failure Analysis



Root Cause Failure Analysis

